



Inspected by **Mike Banks**

Visual/~~Operational~~

Signed

Date 17th October 2025


✓ = OK

X1 = Low Risk





Action as soon as practical

X2 = High Risk








Immediate action

| | | Comments | |
|----------------------------|----|---|---|
| Play Park Access | | | |
| Access to playpark | ✓ | Grass cut short on access to playpark | |
| Play Park Surface | | | |
| Undamaged | X1 | Safamat showing in several places, Remove swings and re-seed area |  |
| Free from animal excrement | ✓ | | |
| Free from litter | ✓ | | |
| Free from sharp objects | ✓ | | |
| Miscellaneous Issues | ✓ | | |







| Sturdy Swings | | | |
|---|----|---|---|
| Wear on chains <40% | ✓ | | |
| Wear on shackles and bushes | ✓ | | |
| Wear on ropes | X1 | Ropes to basket swing are crossed over needs to be re-hung |  |
| Basket free from defects | ✓ | |  |
| Cradle free from defects | ✓ | | |
| Seat free from defects | ✓ | | |
| Cleanliness of equipment | X1 | Seats require algae cleaning off |  |
| Frame in good condition and stable with no wear on connection points for swings | ✓ | | |
| Miscellaneous issues | X1 | Paint chipped on frame, not a safety issue but needs repair in good weather |  |



| Bosworth Multi Play Unit | | | |
|--------------------------|----|---|---|
| Frame | ✓ | | |
| Steps/handrails | ✓ | |  |
| Slide | ✓ | |  |
| Fort | ✓ | |  |
| Climbing Wall | ✓ | |  |
| Balance beam | ✓ | |  |
| Monkey Ropes/handles | ✓ | |  |
| Miscellaneous issues | X1 | Two plastic plugs missing from bolt holes require replacing source from streetscape |  |



| Sturdy Flying Saucer | | | |
|-----------------------------|----|--|---|
| Bowl damage | ✓ | |  |
| Cleanliness | ✓ | | |
| Stability | ✓ | | |
| Bearings | ✓ | | |
| Miscellaneous issues | ✓ | | |
| Picnic Table | | | |
| Table surface | X1 | Table requires rubbing down and treating to protect integrity |  |
| Seats | X1 | Seats require rubbing down and treating to protect integrity |  |
| Metal framework | X1 | Paintwork chipped around frame Seat frame loose in ground not a danger but needs regrouting |  |
| Miscellaneous Issues | ✓ | | |
| Goal Posts | | | |
| Miscellaneous Comments | ✓ | | |