



Inspected by **Mike Banks**

Visual/Operational—

Signed

M Banks

Date 13th August 2026

✓ = OK

X1= Low Risk

Action as soon as practical

X2 = High Risk

Immediate action

		Comments	
Play Park Access			
Access to playpark	✓	Glass had been found around play park area but had been cleaned up by a member of the public	
Play Park Surface			
Undamaged	X1 ✓	Play park surface is showing signs of wear under swings and around Sturdy flying saucer	
Free from animal excrement	✓		
Free from litter	✓		
Free from sharp objects	✓	Report of Glass around play park, non found had been cleared	



Miscellaneous Issues	✓	Sign ok at moment monitor for fading	
Sturdy Swings			
Wear on chains <40%	✓		
Wear on shackles and bushes	✓	Detailed photos of each bush on last pages	
Wear on ropes	✓	Wire showing under outer core Not dangerous but keep an eye on	
Basket free from defects	✓		
Cradle free from defects	✓		



Seat free from defects	✓		
Cleanliness of equipment	✓		
Frame in good condition and stable with no wear on connection points for swings	✓		
Miscellaneous issues	X1	Paint chipped on frame, not a safety issue but needs repair in good weather	
Bosworth Multi Play Unit			
Frame	✓		
Steps/handrails	✓		



Slide	✓		
Fort	✓		
Climbing Wall	✓		
Balance beam	✓		
Monkey Ropes/handles	✓		



Miscellaneous issues	X1	Two plastic plugs missing from bolt holes require replacing	
Sturdy Flying Saucer			
Bowl damage	✓		
Cleanliness	✓		
Stability	✓		
Bearings	✓		
Miscellaneous issues	X1	Area around bowl has fall protection showing. Not an issue at the moment monitor	
Picnic Table			



Table surface	X1	Table requires rubbing down and treating to protect integrity	
Seats	X1	Seats require rubbing down and treating to protect integrity	
Metal framework	X1	Paintwork chipped around frame Seat frame loose in ground not a danger but needs regrouting	
Miscellaneous Issues	✓		
Goal Posts			
Miscellaneous Comments	✓	No Issues with Goalposts	













			
			