

Appendix 1

Inspected by Mike Banks

Visual/Operational

Signed MBell

Date 29th November 2025

✓ = OK

X1= Low Risk Action as soon as practical

X2 = High Risk Immediate action

			1
		Comments	
Play Park Access			
Access to playpark	>	Grass longer in winter to accommodate wear to surface	
Play Park Surface			
Undamaged	~	Safamat has been repaired and area returfed no swings in place	
Free from animal excrement	~		
Free from litter	>		
Free from sharp objects	>		
Miscellaneous Issues	~		



~		
>		
~	Basket swing has been removed to allow grass to establish	
N/A		
~		
N/A	Seat swing has been removed to allow grass to establish	
X1	Seats require algae cleaning off	
~		
X1	Paint chipped on frame, not a safety issue but needs repair in good weather	Adopted Sept 2025
	V N/A X1	removed to allow grass to establish Seat swing has been removed to allow grass to establish Seats require algae cleaning off Paint chipped on frame, not a safety issue but needs



Bosworth Multi Play Unit			
Frame	~		
Steps/handrails	~		
Slide	~		
Fort	~		
Climbing Wall	~		
Balance beam	~		
Monkey Ropes/handles	~		
Miscellaneous issues	X1	Two plastic plugs missing from bolt holes require replacing	



Sturdy Flying Saucer			
Bowl damage	~		
Cleanliness	~		
Stability	~		
Bearings	~		
Miscellaneous issues	~		
Picnic Table			
Table surface	X1	Table requires rubbing down and treating to protect integrity	
Seats	X1	Seats require rubbing down and treating to protect integrity	
Metal framework	X1	Paintwork chipped around frame Seat frame loose in ground not a danger but needs regrouting	
Miscellaneous Issues	~		
Goal Posts			
Miscellaneous Comments	~		