



Inspected by **Mike Banks**

~~Visual~~/Operational

Signed

Date 29th December 2025


✓ = OK

X1= Low Risk





Action as soon as practical

X2 = High Risk





Immediate action

		Comments	
Play Park Access			
Access to playpark	✓	Grass not cut in winter	
Play Park Surface			
Undamaged	✓	Safamat has been repaired and area returfed no swings in place	
Free from animal excrement	✓		
Free from litter	✓		
Free from sharp objects	✓		
Miscellaneous Issues	✓		







Sturdy Swings			
Wear on chains <40%	✓	As per previous quarterly inspection no wear on bushes on swings	
Wear on shackles and bushes	✓		
Wear on ropes	✓		
Basket free from defects	N/A		
Cradle free from defects	✓		
Seat free from defects	N/A	Seat swing has been removed to allow grass to establish	
Cleanliness of equipment	X1	Seats require algae cleaning off	
Frame in good condition and stable with no wear on connection points for swings	✓		
Miscellaneous issues	X1	Paint chipped on frame, not a safety issue but needs repair in good weather	



Bosworth Multi Play Unit			
Frame	✓		
Steps/handrails	✓		
Slide	✓		
Fort	✓		
Climbing Wall	✓		
Balance beam	✓		
Monkey Ropes/handles	✓		
Miscellaneous issues	X1	Two plastic plugs missing from bolt holes require replacing	



Sturdy Flying Saucer			
Bowl damage	✓		
Cleanliness	✓		
Stability	✓		
Bearings	✓		
Miscellaneous issues	✓		
Picnic Table			
Table surface	X1	Table requires rubbing down and treating to protect integrity	
Seats	X1	Seats require rubbing down and treating to protect integrity	
Metal framework	X1	Paintwork chipped around frame Seat frame loose in ground not a danger but needs regrouting	
Miscellaneous Issues	✓		
Goal Posts			
Miscellaneous Comments	✓		