

Playpark Inspection Sheet

Appendix 1

Inspected by Mike Banks

Visual/Quarterly

Signed

Date 12th September 2025

✓ = OK

X1= Low Risk Action as soon as practical

X2 = High Risk Immediate action

		O a ma ma a mata	
		Comments	
Play Park Access			
Access to playpark	~	Grass cut short on access to playpark	
Play Park Surface			
Undamaged	X1	Safamat showing in several places	
Free from animal excrement	~		
Free from litter	~		
Free from sharp objects	~		
Miscellaneous Issues	~		



Sturdy Swings			
Wear on chains <40%	~		
Wear on shackles and bushes	~	Bushes checked on Basket, seat and cradle swings	
Wear on ropes	X1	Ropes to basket swing are crossed over needs to be re-hung	
Basket free from defects	~		
Cradle free from defects	~		
Seat free from defects	~		
Cleanliness of equipment	X1	Seats require algae cleaning off	
Frame in good condition and stable with no wear on connection points for swings	~		
Miscellaneous issues	X1	Paint chipped on frame, not a safety issue but needs repair in good weather	



Bosworth Multi Play Unit			
Frame	~		
Steps/handrails	~		
Slide	~		
Fort	~		
Climbing Wall	~		
Balance beam	~		
Monkey Ropes/handles	~		1-1-3-1-1
Miscellaneous issues	X1	Two plastic plugs missing from bolt holes require replacing source from streetscape	



Sturdy Flying Saucer			
Bowl damage	~		
Cleanliness	~		
Stability	~		
Bearings	~		
Miscellaneous issues	~		
Picnic Table			
Table surface	X1	Table requires rubbing down and treating to protect integrity	
Seats	X1	Seats requires rubbing down and treating to protect integrity	
Metal framework	X1	Paintwork chipped around frame Seat frame loose in ground not a danger but needs regrouting	
Miscellaneous Issues	~		
Goal Posts			
Miscellaneous Comments	~		