



Inspected by **Mike Banks**

Visual/~~Operational~~

Signed *M Banks*

Date 11<sup>th</sup> May 2026

✓ = OK

X1= Low Risk      Action as soon as practical

X2 = High Risk      Immediate action

|                            |   | Comments                                             |  |
|----------------------------|---|------------------------------------------------------|--|
| <b>Play Park Access</b>    |   |                                                      |  |
| Access to playpark         | ✓ | Paths cut into green and grass cut in play park area |  |
| <b>Play Park Surface</b>   |   |                                                      |  |
| Undamaged                  | ✓ |                                                      |  |
| Free from animal excrement | ✓ |                                                      |  |
| Free from litter           | ✓ |                                                      |  |
| Free from sharp objects    | ✓ |                                                      |  |
| Miscellaneous Issues       | ✓ |                                                      |  |



| <b>Sturdy Swings</b>                               |   |  |                                                                                       |
|----------------------------------------------------|---|--|---------------------------------------------------------------------------------------|
| Wear on chains <40%                                | ✓ |  |                                                                                       |
| Wear on shackles and bushes                        | ✓ |  |                                                                                       |
| Wear on ropes                                      | ✓ |  |                                                                                       |
| Basket free from defects                           | ✓ |  |   |
| Cradle free from defects                           | ✓ |  |                                                                                       |
| Seat free from defects                             | ✓ |  |  |
| Cleanliness of equipment                           | ✓ |  |                                                                                       |
| Frame in good condition and stable with no wear on | ✓ |  |                                                                                       |



|                                 |    |                                                                             |                                                                                       |
|---------------------------------|----|-----------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| connection points for swings    |    |                                                                             |                                                                                       |
| Miscellaneous issues            | X1 | Paint chipped on frame, not a safety issue but needs repair in good weather |    |
| <b>Bosworth Multi Play Unit</b> |    |                                                                             |                                                                                       |
| Frame                           | ✓  |                                                                             |                                                                                       |
| Steps/handrails                 | ✓  |                                                                             |   |
| Slide                           | ✓  |                                                                             |  |
| Fort                            | ✓  |                                                                             |  |



|                             |    |                                                             |                                                                                       |
|-----------------------------|----|-------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Climbing Wall               | ✓  |                                                             |    |
| Balance beam                | ✓  |                                                             |    |
| Monkey Ropes/handles        | ✓  |                                                             |   |
| Miscellaneous issues        | X1 | Two plastic plugs missing from bolt holes require replacing |  |
| <b>Sturdy Flying Saucer</b> |    |                                                             |                                                                                       |
| Bowl damage                 | ✓  |                                                             |                                                                                       |
| Cleanliness                 | ✓  |                                                             |                                                                                       |
| Stability                   | ✓  |                                                             |                                                                                       |



|                      |    |                                                                                                |                                                                                       |
|----------------------|----|------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Bearings             | ✓  | No Wear on bearing                                                                             |                                                                                       |
| Miscellaneous issues | X1 | Area around bowl has fall protection showing. Not an issue at the moment                       |    |
| <b>Picnic Table</b>  |    |                                                                                                |                                                                                       |
| Table surface        | X1 | Table requires rubbing down and treating to protect integrity                                  |   |
| Seats                | X1 | Seats require rubbing down and treating to protect integrity                                   |  |
| Metal framework      | X1 | Paintwork chipped around frame<br>Seat frame loose in ground not a danger but needs regrouting |  |



|                        |   |                          |                                                                                     |
|------------------------|---|--------------------------|-------------------------------------------------------------------------------------|
| Miscellaneous Issues   | ✓ |                          |                                                                                     |
| Goal Posts             |   |                          |                                                                                     |
| Miscellaneous Comments | ✓ | No Issues with Goalposts |  |